

## CB2 System - Firmware 1.0 Release Notes

The following document is a list of features implemented with the latest CrewCom® CB2 system firmware release.

### Firmware Details:

<b>Version</b>	1.0.0.15
<b>Release Date</b>	February 16, 2021
<b>Affected Models</b>	CRP-12-900, CRP-12-900AN, CRP-12-2400, CRP-12-2400CE CB2-900, CB2-900AN, CB2-2400, CB2-2400CE

*Compatibility Note: To work together as a system, all CrewCom CB2 system devices must have firmware that matches the version installed on the CB2 BaseStation.*

### Device Parameters

The following number of devices is supported as a single system:

- Up to 2 CB2 BaseStation (sync required for more than one)
- Up to 12 Radio Packs (CRP-12s) (6 per BaseStation)

### Operational Notes

- The CB2-900AN and CRP-12-900AN (Oceania) models operate within the 915–928 MHz frequency range.

### IMPORTANT: Firmware Updates

- Pliant's Firmware Updater Application, a companion desktop software, should be used to update CB2 system device firmware (CB2 BaseStations and CRP-12 Radio Packs) when required. Additionally, this application allows users to update the firmware on the Pliant 6+6 Drop-In Radio Pack and Battery Charger (PBT-RPC-66) when applicable. Choose between the "CB2 System Devices" tab and the "Battery Chargers" tab within the application, depending on the type of device you need to update.